

### Granite Downtakings – King Edward Steps

I, Graeme Cheyne, take responsibility for the granite as stated below.

Print name: Graeme W Ross

Sign: [Signature]

20.01.2021

Graeme W Cheyne Building Contractors Representative

Print name: CARA MCMURTRIC

Sign: [Signature]

20/01/2021




Balfour Beatty Representative









Step	Description	Image
2.7	Corner cracked	 A close-up photograph of a concrete corner where a diagonal crack has formed. The crack runs from the top-left towards the bottom-right, splitting the concrete into two pieces. The surface is rough and appears to be part of a larger structure.
2.9	Split in two	 A photograph showing a concrete slab that has been split in two by a metal railing. The railing is positioned vertically, and the concrete has broken apart, with one piece shifted away from the other. The ground is covered with dry grass and debris.
2.10	Corner cracked	 A close-up photograph of a concrete corner with a diagonal crack. The crack is similar to the one in step 2.7, running from the top-left towards the bottom-right. The concrete is broken and the crack is deep. There is some debris and dry grass around the crack.





### Granite Downtakings – Wall Part 2

I, Graeme Cheyne, take responsibility for the granite as stated below.

Print name: KLEVIN ROSS  
Sign: *[Signature]*  
20.01.2021  
Graeme W Cheyne Building Contractors Representative

Print name: CARA MCMURTRIE  
Sign: *[Signature]*  
20/01/2021  
Balfour Beatty Representative

















### Granite Downtakings – Wall

I, Graeme Cheyne, take responsibility for the granite as stated below.

Print name: KEVIN ROSS  
Sign: Kevin Ross  
15/1/21  
Graeme W Cheyne Building Contractors Representative

Print name: CARA MCNURTRE  
Sign: Cara McNurtre  
15/1/21  
Balfour Beatty Representative













































