

## RE: - Application for SEV Licence - Number7 7 Crown Street Aberdeen AB11 6HA

Following inspection, the items noted below require attention  
David

### **1, Emergency Lighting**

Additional emergency lighting is required to illuminate the main flights of the escape stair which is entered next to the toilets

Emergency lighting is also required to the VIP section and the steps down from this to central bar area

An emergency light is required to illuminate the directional escape sign above the curtain to changing area at side of stage

### **2, Fire Escape signage**

The sign above curtain should be changed to have an up arrow to show that escape is through to the escape stair beyond ( currently arrow points towards bar)

### **3. Holes to walls and ceilings**

Holes were noted to the walls of escape stairs and to ceiling of Ladies toilets, these require to be patched to maintain fire resistance

### **4, Fire doors held open**

It was noted at time of inspection that fire doors were wedged open . Written clarification that this will cease, and that door will be checked as part of safety checks is required

### **5, Bolts to Final exits**

It was noted that there were bolts fitted to final exit push bar doors , these should be removed

### **6, Step to final exit door**

It is noted that fire escape final exit door opens over a step . The edge of step should be painted with a contrasting nosing to aid visual acknowledgement of change in level.

### **RECOMMENDED**

It is recommended that consideration and assessment of the contrasting nosings to internal steps be undertaken with possible improvement to some areas as they may be difficult to distinguish in some lights