

Hello,

Following an inspection of the above, the only observation I noted was the presence of a 'budget lock' on the accessible WC door which for escape purposes I believe should be removed or blanked off- see photo below.



**Kirsty Watt** | Building Standards Officer

Aberdeen City Council | Building Standards | Strategic Place Planning | Place  
Marischal College | Broad Street | Aberdeen | AB10 1AB